

J1	J2	J3	J4	output at entry 0.5 V
- - -	x x	- - -	- - -	0..5V
- - -	x x	- - -	x x	0..10V - power supply must be at least 12V
x x	x x	- - -	- - -	1..5V
x x	x x	- - -	x x	2..10V supply voltage must be at least 12V
- - -	- - -	x x	- - -	0..10mA
- - -	- - -	x x	x x	0..20mA supply voltage must be at least 12V
x x	- - -	x x	- - -	2..10mA
x x	- - -	x x	x x	4..20mA supply voltage must be at least 12V



